

## SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

<b>Date and Time of Notification:</b>	Thursday 13 <sup>th</sup> January 2022, 13:00hrs
<b>Person / Company:</b>	Power and Water Corporation ( <b>PWC</b> )
<b>Incident:</b>	Discharge of sewage from sewerage network (ORG)


<p><b>(a) the incident causing or threatening to cause pollution</b></p>	<p><i>i. Description of the waste that was discharged.</i></p> <p>Partially diluted sewage</p> <p><i>ii. Indicative wastewater quality for the discharge.</i></p> <p>Inflow data to Ludmilla WWTP shows that the average inflow between midnight and 9am 13/01/2022 was 1.0ML/hr, which equates to 23.9ML/day. Rainfall for the previous 48hrs up to 09:00hrs 13/01/2022 was 42.0mm (Darwin Airport – 014015); therefore flows for the day were above average dry weather flows, meaning that the spill was at least partially diluted. Please refer to the following table for indicative wastewater quality.</p> <p style="text-align: center;"><b>Table 1: Inflows to Ludmilla WWTP</b></p> <table border="1"> <thead> <tr> <th></th> <th>Median Inflow (ML)</th> <th>Median E. coli</th> <th>Median Enterococci</th> <th>Dilution Terminology</th> </tr> </thead> <tbody> <tr> <td>below ADWF</td> <td>11.401</td> <td>14,136,000</td> <td>713,550</td> <td>Undiluted</td> </tr> <tr> <td>&gt;ADWF</td> <td>13.253</td> <td>11,616,000</td> <td>727,000</td> <td>Partially Diluted</td> </tr> <tr> <td>&gt;2xADWF</td> <td>29.629</td> <td>8,164,000</td> <td>323,000</td> <td>Diluted</td> </tr> <tr> <td>&gt;3xADWF</td> <td>44.043</td> <td>6,488,000</td> <td>261,300</td> <td rowspan="3">Highly diluted</td> </tr> <tr> <td>&gt;4xADWF</td> <td>51.048</td> <td>5,634,500</td> <td>238,100</td> </tr> <tr> <td>&gt;5xADWF</td> <td>99.841</td> <td>2,359,000</td> <td>218,700</td> </tr> </tbody> </table> <p>NOTE: Based on 01/01/2018 to 31/12/2020 inflows to Ludmilla WWTP and monitoring events data. Average dry weather inflow being 11.9012 ML/day.</p>		Median Inflow (ML)	Median E. coli	Median Enterococci	Dilution Terminology	below ADWF	11.401	14,136,000	713,550	Undiluted	>ADWF	13.253	11,616,000	727,000	Partially Diluted	>2xADWF	29.629	8,164,000	323,000	Diluted	>3xADWF	44.043	6,488,000	261,300	Highly diluted	>4xADWF	51.048	5,634,500	238,100	>5xADWF	99.841	2,359,000	218,700
		Median Inflow (ML)	Median E. coli	Median Enterococci	Dilution Terminology																													
below ADWF	11.401	14,136,000	713,550	Undiluted																														
>ADWF	13.253	11,616,000	727,000	Partially Diluted																														
>2xADWF	29.629	8,164,000	323,000	Diluted																														
>3xADWF	44.043	6,488,000	261,300	Highly diluted																														
>4xADWF	51.048	5,634,500	238,100																															
>5xADWF	99.841	2,359,000	218,700																															
<p><b>(b) the place where the incident occurred</b></p>	<p><i>iii. Volume of the waste that was discharged.</i></p> <p>The volume of waste discharged is unknown. No telemetric monitoring occurs at the site of discharge.</p> <p><i>i. Description of the PWC asset from which the discharge occurred.</i></p> <p>Overflow relief gully (ORG), at 44 Philip Street, Fannie Bay (Lot 1780)</p> <p><i>ii. GPS coordinates of the discharge point from the PWC asset, and the final coordinates of the final discharge point.</i></p>																																	

	<p><i>Approximate locations are as follows;</i>  Discharge Point: 130.8371422E, -12.4198314S (ORG)  Final Discharge Point: 130.8370558E, -12.4198746S (driveway's stormwater drain)</p> <p><i>iii. Indicate any locations nearby to the discharge point where public can gain ready-access, such as public open spaces through which the discharge moves.</i></p> <p>As this spill was contained within the residential property bounds, there is no public access to the spill site.</p>
<p><b>(c) the date and time of the incident</b></p>	<p><i>i. The time and date of commencement and cessation of the discharge.</i></p> <p>The commencement time of the overflow is unknown, but is believed to be less than an hour before being attended to by PWC staff, based on the low volume that had overflowed. The overflow was observed at approximately 09:00hrs by PWC staff on 13/01/2022 and the spill stopped by 09:15hrs 13/01/2022.</p> <p><i>ii. How PWC were notified, or became aware of the discharge.</i></p> <p>This overflow was reported by one of the residents to the PWC call centre, who then relayed the information to the PWC sewer reticulation team that attended the site at 09:00hrs (13/01/2022) and undertook action to resolve the situation and make it safe.</p> <p><i>iii. The process by which the discharge occurred.</i></p> <p>The cause of the spill was due to a partial blockage in the sewer line, which resulted from a build-up of what most likely was fats and non-degradable wipes. Fat and other non-disintegrating items like wet wipes and kitchen paper towels have been incorrectly disposed of into the sewer network by customers, resulting in the blockage and the overflow.</p> <p>When fats and oils are poured down the sink it is usually as a liquid, but as it cools it can become more solid and cause build-up, resulting in bad odours and blockages in the sewerage system. This can lead to the sewage overflows into the environment, households and businesses.</p> <p>Public education about what can be disposed in sewer/is flushable: <a href="https://www.powerwater.com.au/about/what-we-do/wastewater/sewer-blockages-and-overflows/think-before-you-put-it-down-the-sink">https://www.powerwater.com.au/about/what-we-do/wastewater/sewer-blockages-and-overflows/think-before-you-put-it-down-the-sink</a>  In the aim of prevention, this material is available on the PWC website and is used as an educational tool for customers.</p> <p><i>iv. The reason why the discharge occurred.</i></p> <p>As per (c) iii. Sewerage network infrastructure has been designed to overflow with the best public health and environmental outcomes possible. Design focuses on not overflowing directly inside houses; rather discharge is designed to occur in a controlled manner at locations which can be accessed for infrastructure repair and clean up and with minimal public health or environmental impacts.</p>

<b>(d) how the pollution has occurred, is occurring or may occur</b>	As per (c) iii & (c) iv.
<b>(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident</b>	<p><i>i. Confirmation signage and fencing has been erected, as appropriate.</i></p> <p>No fencing or signage was erected in this instance, as the scene was disinfected and cleaned thoroughly; and the residents who know about the spill are the only ones able to access the spill area.</p> <p><i>ii. Decontamination of the site as appropriate.</i></p> <p>Clean up consistent with Sewage Spills/Overflow Response Work Instruction as appropriate to the location, and to minimise risk to the Environment. Blockage was cleared and upon resolution of the blockage, the site was left in a clean state, free from any gross pollutants and the surrounding surface was cleaned and disinfected.</p>
<b>(f) the identity of the person notifying the NT EPA</b>	PWC Environmental Team on behalf of Water Services

## SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Appendix A – Location map



Appendix B – Photographs of the spill site. First one showing the overflowing ORG and the large amount of non-degradable paper/wipes in the system.

