

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	Monday 05/10/2020 16:00hrs
Person / Company:	Power and Water Corporation (PWC)
Incident:	Discharge of raw sewage from sewerage network (no gross pollutants)

(a) the incident causing or threatening to cause pollution	<i>i. Description of the waste that was discharged.</i> Raw sewage (no gross pollutants) <i>ii. Indicative wastewater quality for the discharge.</i> Inflow data to Ludmilla WWTP was 11.3ML/day, and rainfall leading up to the overflow was 0mm for the preceding 3 days (Darwin Airport – 014015), meaning that flows were average dry weather flows, with no dilution. Please refer to the following table for indicative wastewater quality. Table 1: Inflow to Ludmilla Wastewater Treatment Plant <table><tr><th>Inflow volume</th><th>median inflow kL</th><th>median E coli</th><th>90th percentile inflow kL</th><th>90th percentile E coli</th></tr><tr><td>below ADWF</td><td>11,040</td><td>11,199,000</td><td>12,925</td><td>15,531,000</td></tr><tr><td>>ADWF (14.5 ML/day)</td><td>15,274</td><td>9,804,000</td><td>22,206</td><td>17,148,300</td></tr><tr><td>>2x ADWF (29.0 ML/day)</td><td>31,673</td><td>4,884,000</td><td>37,166</td><td>14,385,600</td></tr><tr><td>>3x ADWF (43.5 ML/day)</td><td>43,629</td><td>4,611,000</td><td>50,506</td><td>12,843,600</td></tr><tr><td>>5x ADWF (72.5 ML/day)</td><td>71,558</td><td>5,002,000</td><td>78,578</td><td>5,905,200</td></tr><tr><td>>WDL limit (89.5 ML/day)</td><td>102,445</td><td>102,445</td><td>148,575</td><td>13,704,400</td></tr></table> (ADWF= Average Dry Weather Flow ~14.5 ML/day in 2013/14) <i>iii. Volume of the waste that was discharged.</i> The volume of waste discharged is unknown. No telemetric monitoring occurs at the site of discharge. The affected area was approximately 4 square meters.	Inflow volume	median inflow kL	median E coli	90th percentile inflow kL	90th percentile E coli	below ADWF	11,040	11,199,000	12,925	15,531,000	>ADWF (14.5 ML/day)	15,274	9,804,000	22,206	17,148,300	>2x ADWF (29.0 ML/day)	31,673	4,884,000	37,166	14,385,600	>3x ADWF (43.5 ML/day)	43,629	4,611,000	50,506	12,843,600	>5x ADWF (72.5 ML/day)	71,558	5,002,000	78,578	5,905,200	>WDL limit (89.5 ML/day)	102,445	102,445	148,575	13,704,400
	Inflow volume	median inflow kL	median E coli	90th percentile inflow kL	90th percentile E coli																															
	below ADWF	11,040	11,199,000	12,925	15,531,000																															
	>ADWF (14.5 ML/day)	15,274	9,804,000	22,206	17,148,300																															
>2x ADWF (29.0 ML/day)	31,673	4,884,000	37,166	14,385,600																																
>3x ADWF (43.5 ML/day)	43,629	4,611,000	50,506	12,843,600																																
>5x ADWF (72.5 ML/day)	71,558	5,002,000	78,578	5,905,200																																
>WDL limit (89.5 ML/day)	102,445	102,445	148,575	13,704,400																																
(b) the place where the incident occurred	<i>i. Description of the PWC asset from which the discharge occurred.</i> Overflow relief gully (ORG) at 15 Henry Street, Stuart Park. <i>ii. GPS coordinates of the discharge point from the PWC asset, and the final coordinates of the final discharge point.</i> Discharge Point: 130.8437150, -12.4465410 Final Discharge Point: Immediately surrounding ORG, point of discharge																																			

	<i>iii. Indicate any locations nearby to the discharge point where public can gain ready-access, such as public open spaces through which the discharge moves.</i> There is no public access to the spill site, as it occurred on private property. All residents at the property have been made aware of the spill and advised to avoid contact with the area.
(c) the date and time of the incident	<i>i. The time and date of commencement and cessation of the discharge.</i> The commencement time of the overflow is unknown. The overflow was observed at approximately 11:00hrs by PWC staff on 05/10/2020 and the spill stopped by 11:25hrs 05/10/2020. <i>ii. How PWC were notified, or became aware of the discharge.</i> This overflow was reported by one of the residents to the PWC call centre, who then relayed the information to the on-call PWC operations staff. PWC personnel attended the site at 11:00hrs (05/10/20) and undertook action to resolve the situation and make it safe. <i>iii. The process by which the discharge occurred.</i> The cause of the spill was due to a blockage in the nearby main line, caused by a build-up of fat. Fat and other substances have been incorrectly disposed of into the sewer network by customers, resulting in the blockage and the overflow. When fats, oils and meat juices are put down the sink it is usually as a liquid, but as it cools it can become more solid and cause build-up, resulting in bad odours and blockages in the sewerage system. This can lead to the sewage overflows into the environment, households and businesses. Public education about what can be disposed in sewer/is flushable: https://www.powerwater.com.au/about/what-we-do/wastewater/sewer-blockages-and-overflows/think-before-you-put-it-down-the-sink In the aim of prevention, this material is available on the PWC website and is used as an educational tool for customers. <i>iv. The reason why the discharge occurred.</i> As per (c) iii.
(d) how the pollution has occurred, is occurring or may occur	As per (c) iii & (c) iv.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	<i>i. Confirmation signage and fencing has been erected, as appropriate.</i> No signage or fencing was erected in this instance, as the spill occurred at a fenced, private residence. All residents residing there were advised to avoid contact with the area. <i>ii. Decontamination of the site as appropriate.</i> Clean up consistent with Sewage Spills/Overflow Response Work Instruction as appropriate to the location, and to minimise risk to the Environment. Site inspected for any gross pollutants of which none were observed, and the surrounding surface was cleaned. Landholders

	advised not to enter affected areas for a minimum of 5 days after clean up.
(f) the identity of the person notifying the NT EPA	PWC Environmental Team on behalf of Water Services

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Appendix A – Location map

