

SECTION 14 INCIDENT REPORT (Waste Management and Pollution Control Act)

Date and Time of Notification:	Tuesday 19/11/2019 13:00hrs
Person / Company:	Power and Water Corporation (PWC)
Incident:	Leaking power transformers

(a) the incident causing or threatening to cause pollution	Two large power transformers that are leaking transformer oil, stored outside of the facilities bunded storage area.
(b) the place where the incident occurred	Power and Water Corporation's transformer laydown, within the Ben Hammond complex, Illife Street, Stuart Park.
(c) the date and time of the incident	The leaking assets were noticed on the morning of Monday the 18 th November 2019 by a Power Services employee conducting works in the area at approximately 11:30 hrs.
(d) how the pollution has occurred, is occurring or may occur	Transformer oil is leaking from two power transformers brought in from the field that were incorrectly placed outside the bunded storage compound, where they have leaked an unknown quantity of transformer oil onto an engineered hardstand surface
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	The area of the spill will be covered with plastic sheeting to prevent rain from further spreading any contamination and leaking oil will be captured by placing tubs underneath to capture any additional leaking oil. Discussions with management to determine what additional actions need to be taken are underway. At present, we are looking at increasing the size of the bunded area and mobilising a crane to move these assets to this area of containment, prior to undertaking remediation works.
(f) the identity of the person notifying the NT EPA	PWC Environmental Team on behalf of Service Delivery



SECTION 14 INCIDENT REPORT (Waste Management and Pollution Control Act)



