

**SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)**

<b>Date and Time of Notification:</b>	13/12/14 (time - not recorded)
<b>Person / Company:</b>	Department of Police, Fire and Emergency Services – Berrimah. Ref no. F14012981
<b>Incident:</b>	Truck collision with a prime mover at the intersection of Berrimah Road and Export drive resulting in as hydrocarbon spill.
<b>(a) the incident causing or threatening to cause pollution</b>	Truck collision with a prime mover at the intersection of Berrimah Road and Export drive resulting in as hydrocarbon spill.
<b>(b) the place where the incident occurred</b>	Corner of Berrimah Road and Export Drive - East Arm
<b>(c) the date and time of the incident</b>	13th December 2014
<b>(d) how the pollution has occurred, is occurring or may occur</b>	<p>The spill occurred upon a grass verge, approximately 10m away from the nearest vegetation, a stand of Pandanus. Downslope from the spill is a stormwater drain which is covered by a steel grid. This drain is situated within the grass road verge itself. The slope is shallow. Less than two metres away in the kerb, is a side inlet stormwater drain. The kerb is very slightly upslope from the spill.</p> <p>The incident occurred during the Top End wet season.</p> <p>A potentially significant but unknown volume of hydrocarbons has been released into surrounding soil, down the gutter and into nearby stormwater drains.</p>

<p><b>(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident</b></p>	<p>On 8 January 2015 at 10:30am, DoI conducted a site visit at the reported location.</p> <p>On the same day a desktop assessment was undertaken by DOI. A report was submitted to the NT EPA containing information gained during the site inspection and the desktop assessment.</p> <p>On 29 January 2015 DoI advised that an area off the north-western corner of the intersection, approximately 4m x 2m x 150mm, has been identified for off-site disposal and as such, a Waste Classification Report for submission to a suitably licensed landfill is required.</p> <p>On Thu 12 February 2015 9:04 AM DOI advised that all contaminated soil has been removed and disposed of accordingly, and that the site is now classified as being remediated, and the incident as recorded in DoI has now been closed out.</p>
<p><b>(f) the identity of the person notifying the NT EPA</b></p>	<p>Initially reported by: Department of Police, Fire and Emergency Services – Berrimah</p> <p>Subsequently reported by Department of Infrastructure (DoI).</p>