

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	27/12/17 1600hrs
Person / Company:	Quinten Pope Plantation Management Partners for Tiwi Plantation Corporation
Incident:	Tannin water release
(a) The incident causing or threatening to cause pollution	On 27 th December tannin water was observed leaving the chip pile leaching across the road and entering a native buffer. The road has been in place for the last two years and has not been modified in any way.
(b) The place where the incident occurred	Port Melville Tiwi Island
(c) The date and time of the incident	27th December 2017 Made aware of the breach at 1600hrs
(d) How the pollution has occurred, is occurring or may occur	Tannin from woodchip stockpiles was leaching into the road and got caught on a roll over and filtered into a native strip.
(e) The attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	The flow rate would have been under 650 mils a minute. It took approximately 15 minutes to reshape the road to keep the leaching from entering the native buffer. Tomorrow a grader will reach site and put in a drain on the inside of the road closest to the chip pile making sure the leachate makes it way down the drain to our new basin 1a where it can then be pumped up into basin 4. From the time of being made aware of the situation until stopping the leaching was 1.5hrs.

(f) The identity of the person notifying the NT EPA	Quinten Pope 0428888280 or 89783773
--	-------------------------------------