

SECTION 14 INCIDENT REPORT (Waste Management and Pollution Control Act)

Date and Time of Notification:	25 November 2019 0940hrs. Initial report submitted.
Person / Company:	Cameron Dawe/Sea Swift
Incident:	Light Diesel Spill

(a) the incident causing or threatening to cause pollution	Internal Vessel Fuel Transfer LCT Malu Explorer Official No: 855287
(b) the place where the incident occurred	Darwin Sea Swift Berth No1.
(c) the date and time of the incident	25 November 2019 0855hrs.
(d) how the pollution has occurred, is occurring or may occur	Vessel Internal Fuel Transfer Process. Transferring fuel from ships tank to ship's day tank. An internal investigation is underway to find cause. Initially it appears to be human error.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Vessel & Berth Emergency spill equipment was deployed by crew. *A boom was run out across the berth pocket, then absorbent pads were used to soak up diesel from the surface. All waste material has been bagged & placed aside awaiting collection by Cleanaway. They have assured they can remove & dispose of the waste. Process will employ second person to maintain watch of day tank breather during transfer. A container will be placed under the breather in the event it is ever required.
(f) the identity of the person notifying the NT EPA	Cameron Dawe NT Marine Superintendent.

*Photo of the boom & clean-up in progress

