

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	23/12/16 0800hrs
Person / Company:	Craig Phillips Plantation Management Partners for Tiwi Plantation Corporation
Incident:	Tannin water mixed with storm water release
(a) the incident causing or threatening to cause pollution	Over a 3 day period being 19 th , 20 th and 21 st December Port Melville site received in excess of 250mm of rainfall in a short space of time. The bureau of meteorology issued 5 extreme warnings for the Tiwi island during this period. Joseph Taylor attended site on the afternoon of 22 nd and found that bund 1 had overflowed, as expected with this level of rainfall it was highly diluted.
(b) the place where the incident occurred	Port Melville Tiwi Island
(c) the date and time of the incident	19 th , 20 th and 21 st December 2016
(d) how the pollution has occurred, is occurring or may occur	Tannin from woodchip stockpiles is leaching into port drainage system. This high/heavy rainfall event caused basins to fill and overflow out.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Tiwi Plantation Corporation has engaged EcoZ Environmental to assist in a Tannin Management Plan, the plan is well advanced and is having immediate results. Further engineering is planned this week and is expected to be finished by January 2017
(f) the identity of the person notifying the NT EPA	Craig Phillips 0437 150968