

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	1 st of March 2022 at 11:33 am
Person / Company:	City of Darwin
Incident:	Leachate outside the control bund at GWILP

(a) the incident causing or threatening to cause pollution	Leachate outside the control bund constructed at the GWILP on the eastern side of LP01 and LP02
(b) the place where the incident occurred	GWILP on the eastern side of LP01 and LP02.
(c) the date and time of the incident	Sometime on the 28 th of February 2022
(d) how the pollution has occurred, is occurring or may occur	The earthen bund has exceeded its capacity and allowed leachate to escape.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Veolia are inspecting the area to see if it has dried out enough to get a excavator o construct another perimeter bund around the existing bund. In the interim leachate will continue to be pumped out using a vac truck and transferred back to the leachate pond.
(f) the identity of the person notifying the NT EPA	NT EPA officer while doing a site inspection