

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	26.05.2022 – 10:56AM
Person / Company:	Michael McKee – NORTHLINE
Incident:	Fire inside container. DG Name Hydrogen Peroxide UN2014 – Class 5.1 Sub Class 8 Leaked and burned
(a) the incident causing or threatening to cause pollution	Loss of solution out of containers – possible causes, faulty breather cap, faulty container or a load shift that caused damage to container
(b) the place where the incident occurred	In transit between Adelaide and Alice Springs First awareness of incident when backed onto dock for unloading at Northline Alice Springs Thursday 26.05.2022.
(c) the date and time of the incident	Exact time unknown. Between 9pm 24.05.22 & 7.00am 26.05.22 Discovered at approx. 7am 26.05.22
(d) how the pollution has occurred, is occurring or may occur	Min Pollution occurred – 90% of solution consumed by fire Balance remained in original 25ltr containers Small amount that escaped held in pad area where container unloaded.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	ASP Fire Hazmat team called in to deal with incident. Container unloaded – all items in container that were contaminated washed on exit from container by HAZMAT Team, Solution left in containers emptied into IBC for disposal later by Cleanaway that is 50% full of water. Contaminated water in area where unloading took place was soaked up with spill absorbent and placed into a IBC along with the destroyed mt containers that held the solution Other contaminated water from washing fire crew suits sucked up with a machine into the IBC container that held the contaminated water
(f) the identity of the person notifying the NT EPA	Michael McKee Northline Branch Manager Alice Springs NT 0870