

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	9/1/17 1630hrs
Person / Company:	Power and Water Corporation.
Incident:	Overflow of effluent (highly diluted by catchment rainfall) to specifically designed drains from the pond system, and across road to bushland
(a) the incident causing or threatening to cause pollution	Sewage Overflow from Infiltration Basin for treated effluent Monsoonal event has inundated the sewer system and ponds resulting in an overflow from the pond system via specifically designed overflow weir into the surrounding area.
(b) the place where the incident occurred	Angurugu Infiltration Basin 2
(c) the date and time of the incident	PWC first became aware at 21:50 8/01/17.
(d) how the pollution has occurred, is occurring or may occur	Overflow occurring due to recent heavy rainfall.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	<p>Prevent/Rectify: Incident rectification based on reduction in catchment rainfall levels. Diversion drains in place to direct the effluent from the ponds across the road and into bushland.</p> <p>Control: Staff on site monitoring situation and overflow pathway. Communication program in place including appropriate signage. Mosquito and weed management in place.</p> <p>Clean-up: Overflow is rainfall runoff and diluted treated effluent, minimal clean up expected to be required.</p>
(f) the identity of the person notifying the NT EPA	PWC Environmental Services Team on behalf of Water Services.