

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	0844 h CST 15 November 2017
Person / Company:	Ichthys LNG Pty Ltd
Incident:	Diesel spill from fuel pod

(a) the incident causing or threatening to cause pollution	Diesel spill from fuel pod
(b) the place where the incident occurred	Bladin Point
(c) the date and time of the incident	Became aware 0900 h CST 14 November 2017
(d) how the pollution has occurred, is occurring or may occur	Leak of diesel onto ground and subsequently down rock batter No interaction with natural environment, no pollution, confined to Site.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Applied peat to affected areas Installed earthen bunds to divert stormwater in advance of storm Place absorbent hydrocarbon boom on ground surrounding affected area as precautionary measure Excavation of affected soil
(f) the identity of the person notifying the NT EPA	Jacob Tobin