



SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	09/03/2023 at 10.00 AM
Person / Company:	City of Darwin (EPL188-03)
Incident:	Treated leachate spill on the spillway from the borrow pit and potential seepage of treated leachate on the northern side of the borrow pit
(a) the incident causing or threatening to cause pollution	The treated leachate flowed over the spillway while contractors were working on bund maintenance.
(b) the place where the incident occurred	<p>Spillway on the Northern side of the borrow pit holding treated leachate, Shoal Bay landfill</p> 
(c) the date and time of the incident	08/03/2023 at 10.45 AM

<p>(d) how the pollution has occurred, is occurring or may occur</p>	<p>The spill occurred when the contractors were working onsite on maintaining the bund over the spillway. Currently there is no discharge of treated leachate from the spillway.</p> 
<p>(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident</p>	<p>The spillway has been raised by about 50 mm and there is no further migration of treated leachate over the spillway now. About 1 KL of treated leachate is released into the environment, mainly contained on the spillway.</p> <p>The water samples from the seepage areas have been collected and sent to lab for detail analysis.</p>
<p>(f) the identity of the person notifying the NT EPA</p>	<p>City of Darwin, the Incident was notified to the Pollution Hotline at 10.00 AM on 09/03/23</p>