

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	Initially notified NT EPA via Pollution Hotline 11:49am 24/04/2026
Person / Company:	Liane Tempest-Wilson Ampol Australia Petroleum Pty Ltd
Incident:	First time detection of light non-aqueous phase liquid (LNAPL) in a groundwater monitoring well during six-monthly routine groundwater monitoring well gauging conducted on 24/04/26.

(a) the incident causing or threatening to cause pollution	Underground Petroleum Site Storage (UPSS)
(b) the place where the incident occurred	Ampol Teppa Hill Service Station 3/34 Stuart Highway, Ciccone-Alice Springs NT 0870
(c) the date and time of the incident	24/04/2026 9:30am
(d) how the pollution has occurred, is occurring or may occur	Leak from Underground Petroleum Site Storage (UPSS)
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	LNAPL is currently being investigated to confirm the source and extent. A sample of the LNAPL has been collected and will be fingerprinted to confirm the fuel type (laboratory results are anticipated within 4–6 weeks). Statistical Inventory Reconciliation Analysis (SIRA) has been reviewed, with no failed results recorded for any fuel grades over the past 12 months. This indicates no evidence of a fuel storage system integrity issue or an acute loss of containment from the storage system during this period. A proactive equipment integrity test will be conducted at the site to reaffirm the integrity of the fuel storage system, followed by groundwater monitoring and baildown testing. Subject to the outcomes of these activities, an LNAPL recovery extraction event may be undertaken, along with a detailed environmental investigation to delineate the extent of contamination and assess potential risks to human health and the environment.
(f) the identity of the person notifying the NT EPA	Liane Tempest-Wilson Ampol Australia Petroleum Pty Ltd