

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	Friday 18 December 2015 9.34am
Person / Company:	PWC Environmental Services Team on behalf of Remote Operations
Incident:	Angurugu Sewer Overflow 17/12/15
(a) the incident causing or threatening to cause pollution	Sewage overflow
(b) the place where the incident occurred	Angurugu sewer ponds – infiltration basin 1
(c) the date and time of the incident	First observed at 8.00am 17/12/15 and is still overflowing.
(d) how the pollution has occurred, is occurring or may occur	Treated sewage effluent overflow.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Second infiltration basin brought online to reduce chance of further spills. Temporary diversion drains had been put in place to direct the effluent from the ponds across the road and into bushland. Note: Road is a secondary mine access road, not a public road, so minimal to no human contact. Actions consistent with sewage overflow work instruction: • Overflow is tertiary treated effluent, sewage related debris will not be present • Signage is present on only access road to the ponds to warn the public • Mosquito baits and weed control measures have been installed within the drains. Note: Pond system originally constructed and brought online 2012 and designed for nil discharge. PWC and DLGCS investigating short and long term alternatives to alleviate the situation.
(f) the identity of the person notifying	PWC Environmental Services Team on behalf

the NT EPA	of Remote Operations
------------	----------------------