

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	Friday 5 February 2016 10.56am
Person / Company:	PWC Environmental Services Team on behalf of Remote Operations
Incident:	Angurugu sewer overflow - 4/02/16
(a) the incident causing or threatening to cause pollution	Diluted Treated Effluent Overflow
(b) the place where the incident occurred	Angurugu sewer ponds – infiltration basin 2
(c) the date and time of the incident	First became aware at 4.20pm 4/02/16. According to telemetry the overflow began at 10.30pm 3/02/16 and is currently still overflowing
(d) how the pollution has occurred, is occurring or may occur	
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	NOTE: Overflow is currently contained within drainage ditches on PWC site. The overflow has not crossed the access road at this point in time. <i>Actions consistent with sewage overflow Work Instruction</i> • Overflow is tertiary treated effluent, sewage related debris will not be present. • Signage is present on only access road to the ponds to warn the public. Mosquitoes baits and weed control measures have been installed within the drains.
(f) the identity of the person notifying the NT EPA	PWC Environmental Services Team on behalf of Remote Operations