

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	Monday 17/05/2021 01:07pm
Person / Company:	City of Darwin, Lisa Spann
Incident:	Hydraulic oil spill at 65 Bishop Street, Darwin

(a) the incident causing or threatening to cause pollution	Hydraulic oil was spilt from a street sweeper on to the road within the CoD operations compound.
(b) the place where the incident occurred	65 Bishop Street, Winnellie
(c) the date and time of the incident	Saturday 15/05/2021 06:30am
(d) how the pollution has occurred, is occurring or may occur	Hydraulic hose split and leaked fluid
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Damaged plant was taken to internal workshop for repairs. Snow was applied to the spill and picked up by street sweeper. Contaminated snow has been stored and will be disposed of by waste contractor. Spill occurred in the middle of the road. Spill did not go near or into drains.
(f) the identity of the person notifying the NT EPA	Lisa Spann