

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	21/11/2022 at 2.30 PM
Person / Company:	Pema Dorji/City of Darwin (EPL188-03)
Incident:	
(a) the incident causing or threatening to cause pollution	Leachate syphoned through influent lines on BV150 from leachate manifold when unit was shut down and pump powered off, causing overflow of discharge tank and bund. Approximate 100 litres of leachate was spilled 
(b) the place where the incident occurred	Near northern leachate pond area where Benevap operates, Shoal Bay landfill
(c) the date and time of the incident	21/11/2022 at 9 AM PM
(d) how the pollution has occurred, is occurring or may occur	Leachate syphoned through influent lines on BV150 from leachate manifold when unit was shut down and pump powered off, causing overflow of discharge tank and bund. Approximate 100 litres of leachate was spilled
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	The concentrate leachate was scooped from the ground back into discharge tank and the contaminated soil was removed from the site for disposal. Automated solenoid shut-off valve was re-installed on influent line to prevent syphoning into unit when pump is powered off.
(f) the identity of the person notifying the NT EPA	Pema Dorji/City of Darwin. Incident was notified to the Pollution Hotline at 2.30 pm on 21/11/22