

**SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)**

<b>Date and Time of Notification:</b>	18 <sup>th</sup> November 2025; 22:00
<b>Person / Company:</b>	GEMCO Mining Pty. Ltd.
<b>Incident:</b>	Stormwater release.

<b>(a) the incident causing or threatening to cause pollution</b>	Stormwater release from GEMCO Port Facility.
<b>(b) the place where the incident occurred</b>	GEMCO Port Facility (See Figure 1 below).
<b>(c) the date and time of the incident</b>	17/11/2025 at approximately 9:00 AM.
<b>(d) how the pollution has occurred, is occurring or may occur</b>	The failure of stormwater pumps at the GEMCO Port Facility during a rainfall event has resulted in the release of stormwater into Milner Bay.
<b>(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident</b>	Faults were cleared on pump control units and pumps were restarted which prevented any further release after approximately one hour.  Samples were collected of the stormwater and will be sent to an external laboratory for analysis.
<b>(f) the identity of the person notifying the NT EPA</b>	Michael Smith (Manager Technical Services)

**SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)**



**Figure 1:** Locations of stormwater release.