

## **SECTION 14 INCIDENT REPORT (Waste Management and Pollution Control Act)**

Date and Time of Notification:	3.30pm 4 <sup>th</sup> February 2022
Person / Company:	City of Darwin
Incident:	Shoal Bay Waste Management Facility surface water leaving site from stage 6B has exceeded water quality triggers outlined in attachment 3 surface water monitoring program EPL188-03

(a) the incident causing or threatening to cause pollution	Water samples taken from stage 6B dewatering pipe have exceeded some trigger values in EPL188-03.
(b) the place where the incident occurred	Eastern end of stage 6B landfill
(c) the date and time of the incident	3:00 pm 4th of February 2022
(d) how the pollution has occurred, is occurring or may occur	Surface water running off the landfill surface that has intermediate capping on top has become contaminated.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	The discharge point is now being blocked to prevent surface water from stage 6B entering the stormwater drain.
(f) the identity of the person notifying the NT EPA	Shane Coleman