

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	10 th May 2022, 11:22 am, Pollution Hotline Notified at
Person / Company:	Mick Atkin, Veolia
Incident:	Leachate spill.

(a) the incident causing or threatening to cause pollution	Beneterra return line to the Southern pond has allowed leachate to discharge onto the ground.
(b) the place where the incident occurred	Western side of the southern leachate pond at the entry point to the pond.
(c) the date and time of the incident	10 th of May 2022 at 11:00 am
(d) how the pollution has occurred, is occurring or may occur	The return line was found to have moved up the infeed chute to pond 1, allowing leachate to splash out of the infeed onto the concrete pad.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	<p>Both Beneterra systems were shut down immediately and the area where the spill occurred isolated.</p> <p>The pipe was reinserted back down the infeed injection point deeper into the pond.</p> <p>Veolia and the Beneterra team are now cleaning up the spill estimated to be 20-50 litres of leachate that went to ground.</p>
(f) the identity of the person notifying the NT EPA	Shane Coleman City of Darwin