

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	16/1/17 1000hrs
Person / Company:	Power and Water Corporation.
Incident:	Overflow of effluent (highly diluted by catchment rainfall)
(a) the incident causing or threatening to cause pollution	Sewage Overflow from Infiltration Basin for treated effluent Monsoonal event has inundated the sewer system and ponds resulting in an overflow from the pond system via specifically designed overflow weir into the surrounding area.
(b) the place where the incident occurred	Angurugu Infiltration Basin 2
(c) the date and time of the incident	PWC first became aware at 23:00 16/01/17.
(d) how the pollution has occurred, is occurring or may occur	Overflow occurring due to recent heavy rainfall.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Prevent/Rectify: Incident rectification based on reduction in catchment rainfall levels. Relief points will be disengaged when volumes in the system reduce. Control: Crews monitoring site to manage overflow pathway. Clean-up: Ongoing site monitoring for and clean up of gross pollutants (giving consideration to weather conditions).
(f) the identity of the person notifying the NT EPA	PWC Environmental Services Team on behalf of Water Services.