


SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

| | |
|--|--|
| Date and Time of Notification: | 10/03/2023 at 4.27 PM |
| Person / Company: | City of Darwin (EPL188-03) |
| Incident: | Leachate seepage on interface of Stage 6 and Stage 3 cells |
| (a) the incident causing or threatening to cause pollution | <p>Leachate seepage found at the interface of stage 6 and stage 3</p>  |
| (b) the place where the incident occurred | Interface between stage 6 and stage 3 |
| (c) the date and time of the incident | 10/03/2023 at 12.11 PM |
| (d) how the pollution has occurred, is occurring or may occur | The pollution has been contained and being monitored. |

| | |
|---|--|
| <p>(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident</p> | <p>The downstream drain was banded to prevent leachate movement into the storm water drain and diversion bund was built to contain the seepage. The collected leachate is collected using a vac truck and transferred to the leachate pond.</p>  |
| <p>(f) the identity of the person notifying the NT EPA</p> | <p>City of Darwin, the Incident was notified to the Pollution Hotline at 12.17 PM on 24/02/23</p> |