

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	Tuesday 1 December 2015 4.51pm
Person / Company:	PWC Environmental Services Team on behalf of Remote Operations
Incident:	Angurugu Sewer Overflow 1/12/15
(a) the incident causing or threatening to cause pollution	Sewage overflow
(b) the place where the incident occurred	Angurugu (Lot 580 – Sewer Pump Station 1)
(c) the date and time of the incident	First observed at 6.47am 1/12/15, overflow stopped at 7.27am 1/12/15.
(d) how the pollution has occurred, is occurring or may occur	Combination of raw sewage and partially treated sewage.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Pump repaired. Overflow directly to depression beside pump station. Overflow was contained to land and did not enter any water bodies. Clean up as per PWC overflow response procedure.
(f) the identity of the person notifying the NT EPA	PWC Environmental Services Team on behalf of Remote Operations