

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	22/01/2018
Person / Company:	Aggreko
Incident:	Oil water separator overflow due to power outage

(a) the incident causing or threatening to cause pollution	Drain on wash down pad over flow due to the depot losing power over the weekend. This was due to a lightning strike tripping out the depot power.
(b) the place where the incident occurred	56 Albatross St Winnellie
(c) the date and time of the incident	22/01/18 7:30am
(d) how the pollution has occurred, is occurring or may occur	Hydrocarbons, detergents, degreaser and water that was left in underground tanks has filled with rain water and as a result of the power not being on the oil/water separator pump couldn't pump out the water therefore causing the wash down pad to overflow and run down the back of the yard and into the rear drain.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	Power was reset as soon as we found the problem and spill pads were distributed out to the affected areas, a sweeper truck has been called in to remove all the excess dirt and stone on top of the bitumen and removed from site.
(f) the identity of the person notifying the NT EPA	Kelley Roberts