

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	17/01/2020 approx late morning
Person / Company:	Chris Quince Puma Energy
Incident:	Overflow
(a) the incident causing or threatening to cause pollution	Overflow from septic. non solid waste
(b) the place where the incident occurred	Berrimah Puma Energy
(c) the date and time of the incident	17/01/2020 late morning
(d) how the pollution has occurred, is occurring or may occur	The pump had failed due to switch been tripped from the storm that was in the area

(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	As per photos the plumber was there within 30 minutes from the incident being reported to Puma. The plumber found that the trip switch had tripped from the recent storm cell that went through the area. There was no solid waste to have been split. Also shortly after this there was a large storm front that came through the area  
(f) the identity of the person notifying the NT EPA	Chris Quince Puma Energy Regional NT Manager