

SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)

Date and Time of Notification:	Wednesday, 1 November 2017 3:34 PM
Person / Company:	Snyman VAN STRAATEN / JKC Australia LNG Pty Ltd
Incident:	Seal Primer 'lifting' with the stormwater and flowing into the drain along Wickham Point Road

(a) the incident causing or threatening to cause pollution	Approximately 50-70 litres of Seal primer entered a stormwater drain on Wickham Point Road.
(b) the place where the incident occurred	Intersection of Wickham Point Road and the access road to the Ichthys Project Gas Export Pipeline Beach Valve Station
(c) the date and time of the incident	31 October 2017, 1:00pm
(d) how the pollution has occurred, is occurring or may occur	At 11:00am on 31 October 2017, during the preparation for application of asphalt, approximately 400 litres of Seal Primer was applied to the intersection road area and was completed around 12:20pm. At approximately 1:00pm, a short but heavy rain storm passed over the work area, resulting in a quantity (estimate 50-70 litres) of the Seal Primer 'lifting' with the stormwater and flowing into the drain along Wickham Point Road (refer to Photo 1). Typically, one hour minimum is required for the Seal Primer to cure and not lift. This rain event was unexpected at that time.
(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident	JKC's subcontractor contained the contaminated storm water on the work site by installing a geo-fabric and earth dam bund, and then undertook a swift clean-up to remove all the contaminated water by vacuum truck. Hydrocarbon booms were installed. Zero quantity of contaminated water exited the work site. The distance of drainage that was contaminated is approximately 20 metres. The rock armour and drain lining were further inspected today, 1 November 2017, and further cleaned or replaced. The subcontractor will reinstate the primed grassroots drains, rocks and clean the concrete culverts.
(f) the identity of the person notifying the NT EPA	Shoanne Labowitch / JKC Australia LNG Pty Ltd