

**SECTION 14 INCIDENT REPORT (*Waste Management and Pollution Control Act*)**

<b>Date and Time of Notification:</b>	Date: 03.11.2025 Time: 1:00pm
<b>Person / Company:</b>	Clough BMD Joint Venture (CBJV)
<b>Incident:</b>	Land spill: Hydraulic oil/Transmission fluid leak from Project site.
<b>(a) the incident causing or threatening to cause pollution</b>	Approximately 20L of hydraulic oil and 7.2L of transmission fluid was released from the Project site.  This is based on the amount required to refill the tanks, including the residual volume in the hydraulic line.
<b>(b) the place where the incident occurred</b>	Darwin Ship Lift Project 865 Berrimah Road, East Arm NT 0822
<b>(c) the date and time of the incident</b>	Date: 03.11.2025 Time: 9:40am
<b>(d) how the pollution has occurred, is occurring or may occur</b>	A service team member was driving a water truck from the Project site to Black Cat Civils workshop for repairs / maintenance. At this time, the driver was unaware the truck was leaking oil. Upon investigation, the oil was observed to track from the Project site to the intersection of Berrimah Road and Casey Street.
<b>(e) the attempts made to prevent, reduce, control, rectify or clean up the pollution or resultant environmental harm caused or threatening to be caused by the incident</b>	<b>Control Measures</b> 1. Trafficwex personnel setup traffic cones and road work signs to re-direct traffic to prevent further dispersion of the oil.  <b>Clean-up</b> 1. CBJV personnel applied granular absorbent mix to the area. 2. A posi-track loader was used to collect the excess material. 3. The contaminated absorbent material was placed into an IBC for disposal off-site to a waste facility.

	<ol style="list-style-type: none"><li>4. Industrial Power Sweeping Services applied enviro soluble detergent and commenced works.</li><li>5. Works ceased at 2:30pm due to receiving red warning alert from the Bureau of Meteorology (BOM).</li><li>6. The street sweeper re-commenced works on 04 November along Berrimah Road to focus on sections with remaining oil residue.</li><li>7. The waste collected from the street sweeper will be taken to VTG's facility for disposal.</li></ol>
<b>(f) the identity of the person notifying the NT EPA</b>	Caprice Hyde Environmental Advisor, CBJV