SECTION 14 INCIDENT REPORT

Waste Management and Pollution Control Act 1998

Company / Person	Tim Danby, Territory Generation
Description of Incident	On 24 August 2026, a waste oil tank at Owen Springs Power Station overflowed, releasing approximately 1,500 L of oily water. The spill affected adjacent gravel and soils but remained within the site boundary, with no evidence of off-site impacts.
Date and time of incident	24/8/2026
Location	183 Brewer Rd, Hugh

Immediate actions included stopping the overflow and deploying absorbent materials, spill mats and temporary bunding to contain the release. The affected area was secured and a contractor engaged to remove contaminated soil and gravel.

